

中华人民共和国
住房和城乡建设部

《建筑节能工程施工质量验收规范》
GB 50411-2007

CN ZG G6 Z2 0D23000007 000001



L3A FNA48TYC0063

VIN
GB 17691-2018 b

GB 1495



01	YZ6510YFFB1Z	08	CBD
02		09	
03	M()	10	
04		11	
05	()	12	
06	2	13	R134a
07	B	14	EXI
08	VP2H16CEA2	18	W104H
09		19	B72310118X
10		197	21B

GB 17691-2018

GB 1495-2002

21	GB 3847	()	
22			
23	/	VP0P01/	
24	/	W02DEV/	
25	EGR /		
26	ECU /	WSE10/	
27	CBD		
28		DCC(1)+SCR(1)+ASC(1)+DPF(1)	
29	DCC /	VPDCC01/	
	/ /	()	/ 1: NGK() / 1:
30	SCR /	VPSCR01/	
	/ /	()	/ 1: NGK() ; 2: NGK()
) / 1: () ; 2: ()	
31	ASC /	VPASC01/	
	/ /	()	/ 1: NGK() / 1:
32	DPF /	VPDPF01/	
	/ /	()	/ 1: NGK() / 1:
33	/	FV70-15030202-A1/	
	/		
34			
35			
36	4001-888-666		

<https://qxqc.siotruk.com>

<https://www.vecc.org.cn>

: 2026-01-24